US ERA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared	UNIT LOG	
Kalamazoo River/Enbridge Spill		05/16/2012		1800	ICS 214	
4. <u>Unit Name/Designators</u>		5. Unit Leader		6. Operational Period :		
SOTF Team #1		Name:	Name: Dan Capone & Joe Victory (START/US EPA)		From:	05/16/2012 0800
		Position:	n: Operations Section Chief		То:	05/16/2012 1800
		7. Pe	rsonnel	Roster Assigned		
<u>Name</u>		ICS Position				L
Dan Capone		Operations Section Chief				
Joe Victory		Operations Section Chief				
Dan Zahner		Field Team Lead				
Jose Aguilera		SOTF#1				
		•				
			8. Ac	tivity Log		
				•		
Activity Area					LAT	LAT
	MP7.25-12.50			Various	Various	
		OH DADA	MED		(DD.MMMM)	(DD.MMMM)
OIL OBSERVED	EXTENT OF OIL IMPACTED NA					
				NA		
Total Collection Points	NA					
Total Boom Deployed	NA					
Activity	START SOTF Team #1Activity: SOTF # 1 conducted oversight of Enbridge's Team A poling re-assessment activities. Team A members Mike Neal Poling leader, Russell Patte GPS/Leica operator. Team A conducted poling sediment agitation at several focus areas: 10.80S backchannel setting, 1 poling point with moderate sheen, 3 points with light sheen and 5 points with no visible contamination. 12.50S oxbow setting, 3 points with heavy oil sheen 1 moderate, 13 with light and 15 points with no visible contamination. 7.75A oxbow setting 1 point with heavy oil sheen, 4 with light oil sheen and 8 with no visible contamination. Temperature readings in the sediment ranged from a low of 63 to a high of 68 degrees Fahrenheit. Bed and water temperatures where a few degrees higher reaching up 70 degrees. Areas poled today consisted mostly of sand and gravel with relatively fast flow, however points where the most visible contamination had soft sediment associated with it. Some areas where inaccessible due to receding water level and exposed mudflats.					
Health and Safety Issues	None					

Comments None